



$$\begin{array}{r} 160 \\ 20 \\ \hline 140 \end{array} \quad 27\frac{9}{10}$$

538


Photo H
7x9
1... 3/2
17/3 x 2 3/3
2720

Ottendorfer Library and Stuyvesant Polyclinic
New York, New York
Landmarks Preservation Commission, 1965-Photo
View to the west

Neg: Landmarks Preservation Commission
305 Broadway, New York, NY

#1

NR



LANDMARKS PRESERVATION COMMISSION

305 Broadway, New York, N. Y. 10007

2

Stuyvesant Polyclinic
137 Second Avenue, New York City,
New York County
Photo: Suzanne J. Wilson, 4 1979
Neg: New York City Landmarks
Preservation Commission
Detail of ground floor facade



LANDMARKS PRESERVATION COMMISSION

305 Broadway, New York, N. Y. 10007

#3

Stuyvesant Polyclinic
Stuyvesant Polyclinic
137 Second Avenue, New York City,
New York County
Photo: Suzanne J. Wilson
Negative: New York City Landmarks
Preservation Commission
Main floor facing rear; stairway
with flanking columns



LANDMARKS PRESERVATION COMMISSION


305 Broadway, New York, N. Y. 10007

#4

Stuyvesant Polyclinic
137 Second Avenue, New York City
137 Second Avenue, New York City,
New York County

Photo: Suzanne J. Wilson
Negative: New York City Landmarks
Preservation Commission

Main floor: detail of stairway
with scroll work design and
columns



LANDMARKS PRESERVATION COMMISSION

305 Broadway, New York, N. Y. Y. 10007

Ottendorfer Library
135 Second Avenue, New York City,
New York County

Photo: Suzanne J. Wilson, 1 1979

Neg: New York City Landmarks

Preservation Commission

Detail of ground floor facade

#5



LANDMARKS PRESERVATION COMMISSION

305 Broadway, New York, N. Y. 10007


Ottendorfer Library
135 Second Avenue, New York City,
New York County
Photo: Suzanne J. Wilson
Negative: New York City Landmarks
Preservation Commission
Main floor entrance area with
staircase and part of check-
out desk



LANDMARKS PRESERVATION COMMISSION

305 Broadway, New York, N. Y. 10007-#75

Ottendorfer Library
Ottendorfer Library
135 Second Avenue, New York City,
New York County
Photo: Suzanne J. Wilson
Negative: New York City Landmarks
Preservation Commission
Main floor stacks - facing office
in rear



LANDMARKS PRESERVATION COMMISSION

305 Broadway, New York, N. Y. 10007

#83

Ottendorfer Library

Ottendorfer Library

135 Second Avenue, New York City,
New York County

Photo: Suzanne J. Wilson

Negative: New York City Landmarks
Preservation Commission

2nd Floor children's library with
windows facing Second Avenue