


3 PHOTOGRAPH OF EXISTING CONDITIONS
A-3 SCALE: N.T.S.



4 PHOTOGRAPH OF EXISTING CONDITIONS

SCALE: N.T.S.




5 PHOTOGRAPH OF EXISTING CONDITIONS
A3 SCALE: N.T.S.




6 PHOTOGRAPH OF EXISTING CONDITIONS
SCALE: N.T.S.










5 PART, ELEVATION AT EXISTING VESTIBULE SCALE: N.T.S.







OCTOBER 30, 2013














5 PHOTOGRAPH OF EXISTING CONDITIONS
A-8 SCALE: N.T.S.




6 PHOTOGRAPH OF EXISTING CONDITIONS
SCALE: N.T.S.



7 PHOTOGRAPH OF EXISTING CONDITIONS SCALE: N.T.S.








4 PART. ELEVATION AT ENTRANCE - PROPOSED SCALE: N.T.S.






PROVIDE AND INSTALL WINDOW FRAME TO MATCH

OCTOBER 30, 2013







3 PHOTOGRAPH OF EXISTING CONDITIONS SCALE: N.T.S.



4 PHOTOGRAPH OF EXISTING CONDITIONS
A-7 SCALE: N.T.S.



5 PHOTOGRAPH OF EXISTING CONDITIONS
SCALE: N.T.S.









