

MIDDLE COLLEGIATE CHURCH~1966



CTA ARCHITECTS P.C.

151 West 26th Street - 8th Floor New York, New York 10001-6810 Tel: 212.243.7404 info@ctaarchitects.com NYC LANDMARKS PRESERVATION COMMISSION - PUBLIC HEARING MIDDLE COLLEGIATE CHURCH

Project Address: 50 EAST 7TH STREET, NEW YORK, NEW YORK 10003

SK-01

SCOPE OF WORK:

INSTALLATION OF RTU ON 4TH FLOOR ROOF.



OVERVIEW OF MIDDLE COLLEGIATE CHURCH FACADE, MAIN ENTRANCE (2017)



OVERVIEW OF MIDDLE COLLEGIATE CHURCH FACADE, MAIN ENTRANCE (2023)



50 EAST - 7TH STREET, NEW




CTA ARCHITECTS P.C.

151 West 26th Street - 8th Floor New York, New York 10001-6810 Tel: 212.243.7404 info@ctaarchitects.com NYC LANDMARKS PRESERVATION COMMISSION - PUBLIC HEARING MIDDLE COLLEGIATE CHURCH

Project Address: 50 EAST 7TH STREET, NEW YORK, NEW YORK 10003

SK-02





OVERVIEW OF EXISTING BUILDING.



CTA ARCHITECTS P.C.

151 West 26th Street - 8th Floor New York, New York 10001-6810 Tel: 212.243.7404 info@ctaarchitects.com NYC LANDMARKS PRESERVATION COMMISSION - PUBLIC HEARING

MIDDLE COLLEGIATE CHURCH

Project Address: 50 EAST 7TH STREET, NEW YORK, NEW YORK 10003

SK-03

EXISTING PHOTOGRAPHS



OVERVIEW OF WEST ELEVATION



OVERVIEW OF WEST ELEVATION



CTA ARCHITECTS P.C.

151 West 26th Street - 8th Floor New York, New York 10001-6810 Tel: 212.243.7404 info@ctaarchitects.com NYC LANDMARKS PRESERVATION COMMISSION - PUBLIC HEARING MIDDLE COLLEGIATE CHURCH

Project Address: 50 EAST 7TH STREET, NEW YORK, NEW YORK 10003

SK-04

EXISTING PHOTOGRAPHS



OVERVIEW OF EXISTING SKYLIGHT



OVERVIEW EXISTING CLERESTORY / INTERIOR



CTA ARCHITECTS P.C.

151 West 26th Street - 8th Floor New York, New York 10001-6810 Tel: 212.243.7404 info@ctaarchitects.com NYC LANDMARKS PRESERVATION COMMISSION - PUBLIC HEARING MIDDLE COLLEGIATE CHURCH

Project Address: 50 EAST 7TH STREET, NEW YORK, NEW YORK 10003

SK-05

15 [

EXISTING CONDITION AT 5TH FLOOR ROOF



OVERVIEW OF 5TH FLOOR ROOF




OVERVIEW OF 5TH FLOOR ROOF



OVERVIEW OF 5TH FLOOR ROOF



OVERVIEW OF 5TH FLOOR ROOF



VIEW OF 3RD FLOOR / ROOF BELOW



OVERVIEW OF 5TH FLOOR ROOF



CTA ARCHITECTS P.C.

151 West 26th Street - 8th Floor New York, New York 10001-6810 Tel: 212.243.7404 info@ctaarchitects.com NYC LANDMARKS PRESERVATION COMMISSION - PUBLIC HEARING MIDDLE COLLEGIATE CHURCH

Project Address: 50 EAST 7TH STREET, NEW YORK, NEW YORK 10003

SK-06

EXISTING CONDITION AT 3RD FLOOR ROOF



EXTERIOR / EXISTING CLERESTORY WINDOWS



INTERIOR / EXISTING CLERESTORY WINDOWS



EXISTING EXTERIOR CLERESTORY WINDOWS SIDING



EXISTING CLERESTORY WINDOW CONDITION



EXISTING SKYLIGHT



EXISTING SKYLIGHT



CTA ARCHITECTS P.C.

151 West 26th Street - 8th Floor New York, New York 10001-6810 Tel: 212.243.7404 info@ctaarchitects.com NYC LANDMARKS PRESERVATION COMMISSION - PUBLIC HEARING MIDDLE COLLEGIATE CHURCH

Project Address: 50 EAST 7TH STREET, NEW YORK, NEW YORK 10003

SK-07

SCOPE OF WORK



RENDERING OF WEST ELEVATION WITH SUPER IMPOSED RTU AND DUCTS.




CTA ARCHITECTS P.C.

151 West 26th Street - 8th Floor New York, New York 10001-6810 Tel: 212.243.7404 info@ctaarchitects.com NYC LANDMARKS PRESERVATION COMMISSION - PUBLIC HEARING MIDDLE COLLEGIATE CHURCH

Project Address: 50 EAST 7TH STREET, NEW YORK, NEW YORK 10003

SK-08

SCOPE OF WORK RENDERING



RENDERING OF WEST ELEVATION WITH SUPER IMPOSED RTU AND DUCTS.




CTA ARCHITECTS P.C.

151 West 26th Street - 8th Floor New York, New York 10001-6810 Tel: 212.243.7404 info@ctaarchitects.com NYC LANDMARKS PRESERVATION COMMISSION - PUBLIC HEARING MIDDLE COLLEGIATE CHURCH

Project Address: 50 EAST 7TH STREET, NEW YORK, NEW YORK 10003

SK-09

SCOPE OF WORK






CTA ARCHITECTS P.C.

151 West 26th Street - 8th Floor New York, New York 10001-6810 Tel: 212.243.7404 info@ctaarchitects.com NYC LANDMARKS PRESERVATION COMMISSION - PUBLIC HEARING MIDDLE COLLEGIATE CHURCH

Project Address: 50 EAST 7TH STREET, NEW YORK, NEW YORK 10003

SK-10

EXISTING WEST ELEVATION





CTA ARCHITECTS P.C.

151 West 26th Street - 8th Floor New York, New York 10001-6810 Tel: 212.243.7404 info@ctaarchitects.com NYC LANDMARKS PRESERVATION COMMISSION - PUBLIC HEARING MIDDLE COLLEGIATE CHURCH

Project Address: 50 EAST 7TH STREET, NEW YORK, NEW YORK 10003

SK-11



Unit Rating

Job Information			Unit Information		
Job Name: Job Number: Site Altitude: Refrigerant	Middle Church - Low Sound Condenser Fans Job ≢2022120674 0 ft R-410A		Approx. Op./Ship Weights: Supply CFMESP: Pre-Filter FV / Oty: Final Filter FV / Qty: Exhaust CFMESP/TSP: Outside CFM: Ambient Temperature: Return Temperature:	3784 / 3784 lbs. (±5%) 12250 / 2 in. wg. 588.00 fpm / 6 588.00 fpm / 6 2770 / 0.75 / 1.27 in. wg. 2550 94.9 °F DB / 74.9 °F WB	
Static Pressure					
External: Evaporator: Filters Clean: Dirt Allowance Re-Heat Coil	2.00 in. wg. 0.97 in. wg. 0.85 in. wg. 0.35 in. wg. 0.18 in. wg.		Economizer: Heating: Cabinet: Energy Recovery: Total:	0.34 in. wg. 0.66 in. wg. 0.33 in. wg. 0.38 in. wg. 5.67 in. wg.	
Cooling Section			Heating Section		
	Gross	Net	PreHeat Type:	Std (No Preheat)	
Equivalent Total Capacity: Total Capacity: Sensible Capacity: Latent Capacity: HW Total Cooling Capacity: Mixed Air Temp: Entering Air Temp: Lv Air Temp (Coil): Lv Air Temp (Unit) Digital Comp. Capacity Ratio: Supply Air Fan: SA Fan RPM / Width:	423.59 MBH 341.18 295.06 46.12 MBH 82.40 MBH 76.03 °F DB 76.03 °F DB 53.46 °F DB 57.24 °F DB 100% 1 x 270 ⊕ 18.50 BH 1777 / 5.640°	372.96 MBH 290.56 MBH 244.44 MBH 62.74 °F WB 62.74 °F WB 52.83 °F WB 54.39 °F WB	Heating Type: Heating CFM: Total Capacity: OA Temp: RA Temp: Entering Air Temp: Leaving Air Temp: Input: Heater Oty: Consumption: Total Turndown Ratio:	Nat. Gas Heat 12250 328.1 MBH 0.0 °F DB / 0.0 °F WB 70.0 °F DB / 58.0 °F WI 66.1 °F DB / 58.8 °F WI 90.9 °F DB / 64.8 °F WI 405.0 MBH 1 405.0 MBH 13:1	
Exhaust Air Fan: EA Fan RPM / Width: Evaporator Coil:	1777 / 5.640" 1 x RM220AB70 @ 0.87 BHP 1118 / 3.450" 19.9 ft² / 6 Rows / 12 FPI		Re-Heat Coil: Capacity: LA DB / WB: RH-	213 MBH 69.55 °F / 59.17 °F 54%	

Listing Model: RN-030-3-0-BABY-V0-21-000-A

Cooling Capacity (MBH): Cooling EER: Cooling IEER: Rated in accordance with AHRI 340/360 10.8 13.2

Application EER @ Op. Conditions:

Rating Information

Electrical Data							
Rating:	208/3/60 190			Minin	np: 205	205 250	
Unit FLA:				Maxin	ent: 250		
SCCR:	5 KAI	C					
	Qty	HP	VAC	Phase	RPM	FLA	RLA
Compressor 1:	1		208	3			51.3
Compressor 2:	1		208	3			51.3
Condenser Fans:	3	1.00	208	1	1110	7.4	
Supply Fan:	1	20.00	208	3	1760	59.4	
Exhaust Fan:	1	1.00	208	3	1760	4.6	
Combustion:	2	0.25	208	1	3210	1.7	
Energy Recovery:	1	0.1667	208	1	1075	1.2	


Unit Rating

Cabinet Sound Power L	_eveis^							
Octave Bands:	63	125	250	500	1000	2000	4000	8000
Discharge LW(dB):	99	96	96	100	97	93	90	87
Return LW(dB):	87	88	84	77	77	73	66	59
*Sound power levels are given for inf	ormational purposes o	nly. The sound level	s are not guarantees	i.				


RNC CABINET AIR COOLED CONDENSING UNIT WITH ENERGY RECOVERY SECTION

(AAON*)

RN-030-8-0-EB09-38B:UELC-Q0H-DEM-AGA-0DECLYD-00-HJE0000VB



RN SERIES C - CABINET WITH ECONOMIZER ~ 16-30 TON ENERGY RECOVERY SECTION AND POWER EXHAUST



CTA ARCHITECTS P.C.

151 West 26th Street - 8th Floor New York, New York 10001-6810 Tel: 212.243.7404 info@ctaarchitects.com NYC LANDMARKS PRESERVATION COMMISSION - PUBLIC HEARING MIDDLE COLLEGIATE CHURCH

Disclaimer: This weight estimate does not account for any SPAs.

Project Address: 50 EAST 7TH STREET, NEW YORK, NEW YORK 10003

SK-12